

Making and Using Reamers

part 1

Bill Haneman


D bits

- if end is formed properly, they are self-centering
- require frequent chip clearing
- use relatively slowly
- relatively easy to keep sharp

simple boring tools

- see D.M.Quinn, “Low tech bits”, *Pipes and Pipemaking CD-ROM*


- *parrot-nose bit*



- *D bit*



- *angled nose, relief in cutting edge*



gun drills

- fast, self-centering and cool running
 - still, better finish and centering if not pushed
- chip clearing is automatic
 - ideally want 90-110 psi
 - 3 m³/hr if using larger bits, large reservoir helpful
 - not all the same; get 'modified highland' profile
- different couplings available








using gun drills to step-bore

- bore from large to small
 - small-to-large causes drift, as larger hole tends to run tangent to previous hole
- piloting bits are important
 - there are reports of specially-profiled gun drills that self-pilot large-to-small (pilot on nose)
- remember, speed is overrated
 - even though surface finish for step-boring probably is not important



step drilling (cont.)

- allow for any non-concentricity
 - my approach is to step drill with 0.5mm clearance on sides

fixed steady



socket reamers

- I use commercial left-hand-spiral fluted straight reamers for final reaming of drone sockets and in a few other places
 - hole is pre-bored to at most 1mm undersize
 - only the first mm or so actually cuts
 - reamer should spin slowly, with frequent chip clearing
 - when boring drone sockets, I guide the slide with the tailpiece, onto the reamer (aids parallelism and concentricity)




Making conical reamers

- first decide what your reamer profile(s) should look like
- multiple reamers give flexibility, also solve problem of different tool edge speeds
 - on narrower parts of bore, reamer moves more slowly
 - also easier to correct for a mistake, less work to discard if you screw up

A sample reamer plan

- plan for reamer “steps” of 5-10mm length
 - ‘fit’ this to your target bore(s)
 - check length to allow adjustment, perhaps allow for re-use on a longer chanter?




turn suitable tool steel rod in 'steps'

- chuck securely with minimum overhang
 - collet chucks are ideal, an independent, hand-centered 3-jaw is fine but slow, self-centering 3-jaw probably OK
- first “step” may be a cylindrical 'nose'
 - must be undersize to avoid higher parts of bore
 - helps when clamping piece for milling
- bore pilot hole for tailstock
- nose may need to be turned without tailstock support














one step at a time

- turn each step to the 'maximum' size for the segment, or $\sim 0.001''/0.03\text{mm}$ oversize
- carbide is OK but decent tool steel seems even better, for cutting non-heat-treated rod
- check with micrometer as you go
 - stop the lathe of course









take off the 'steps'


- engineer's bluing is good
- careful not to go undersize
 - can be corrected, painfully, by moving your target diameters laterally
- go slow when only lines remain – abrasives are best at this point
- accuracy will improve with practice, but is limited mostly by your patience





re-measure and fine-tune

- re-measure with micrometer – one with a ratchet is a good idea
 - best is one with flat anvils, but can make do with round ones if you are careful
 - mark the distances from the tip with a thin indelible marker
- check against your target bores, looking for best insertion depth
- you can put back on lathe and adjust with files/abrasives if you don't like the results
 - this is the last chance to fix this, as you can't really do it once the reamer has been milled down to a D profile





(calibrated) vernier micrometer, 0.001mm
increment with ratchet




from 'cone' to reamer

- milling operation only needs to be approximately midline
 - but not over midline!
 - just over 50% thickness allows for sharpening
- initial clamping is tricky, but shims of soft metal should do it
 - there shouldn't be much lateral force on the blank anyway, since cutting speeds and depths should be modest










a “micro-mill” is enough

- or you can use hacksaw (ugh!)
- small throat reamers can be ground on a wet grinder
 - this tends to be hard on wet grinding wheels
- then the result can be filed more flat, if uneven
- then inside can be hollow-ground on wet grinder and dressed with fine stone/hone





with luck, you can re-use reamers for another design...



there are other forms of reamers

- for instance flat reamers
- 'bayonet' reamers
- 'square section' reamers
- fluted reamers
 - spiral fluted reamers that aren't straight are very hard to sharpen
- 'spoon' reamers

John Hughes reamer – 4 straight flutes


- as described in 'A Method of Making Reamers', *Sean Reid Society Journal* v. 2, Mar. 2002



Michael Carney tools







flat reamers

- used to good effect by some makers
- resharpening changes their dimensions
- may be prone to chatter or create 'lobes'
- dimensioning them in the first place can be difficult
 - they cut on the diagonal, which changes with thickness/width ratio

initial reaming a blank

- I like to hold the reamer in the lathe at slow speed (125 RPM or less)
- allows control over blank
- go slow
 - avoid overheating
- clear chips often
 - ditto
- use non-water-bearing lubricant
 - I like linseed oil, have used paste wax

finish reaming

- check bore with gauges to judge final reaming depth
 - reamer insertion depth can be misleading, due to wood movement and elasticity
 - some thermal movement, remember
 - most billets will shrink a bit
 - give some time to settle – months ideally
- hand-ream until spot checks match up
 - you may wish to reduce lubrication at this step, to avoid build-up









cautions

- careful with billets that may have warped
 - ream too gently, and your bore may not match reamer profile
 - use enough pressure, if practical, that the reamer flexes when necessary
 - too much pressure or speed can cause overheating, or even with hand-reaming can cause uneven results due to timber elasticity
 - oval bores can result